


ภาคผนวก ก

ขั้นตอน set หน่วยและการวัดแบบ 3 มิติของชิ้นงาน

ขั้นตอน set หน่วยและการวาดแบบ 3 มิติของชิ้นงาน


รูปที่ 1 Simple part

- เปิดหน้าจอ Part / Solid ของโปรแกรม Pro/ENGINEER 2000i2




รูปที่ ก-1 แสดงหน้าจอแรกเมื่อเข้าสู่โปรแกรม Pro/ENGINEER 2000i2

- ใส่ชื่อ Part01 /OK




รูปที่ ก-2 แสดงการกำหนดชื่อ Part และเข้าสู่โปรแกรม




รูปที่ ก-3 แสดงหน้าจอ Part/Solid ก่อนเข้าสู่คำสั่งการวัดแบบ

- กำหนดระบบหน่วยเป็น มิลลิเมตร โดย *Part / Set up / Units*




รูปที่ ก-4 การกำหนดระบบหน่วยเป็น มิลลิเมตร

- เลือก **millimeter Newton Second (mmNs) / Set / Close**




รูปที่ ก-5 การเลือก millimeter Newton Second

- **Part / Feature / Create / Solid / Protrusion**




รูปที่ ก-6 ขั้นตอนในการวัดแบบ 3 มิติ
- Extrude / Solid / Done / One side / Done




รูปที่ ก-7 ขั้นตอนการวัดแบบ 3 มิติ

- กดลูกศรที่ Plane **Front / OK / Top** / กดลูกศรที่ Plane **Top / Close**



รูปที่ ก-8 แสดงการกำหนดทิศทางของ Plane Front ที่ใช้วัดแบบ




รูปที่ ก-9 หน้าจอที่พร้อมสำหรับการวาดแบบ

ภาคผนวก ข

โปรแกรม Microsoft Visual Basic 6.0 ช่วยในการเขียนโปรแกรมแบบ CL file Data

โปรแกรม Microsoft Visual Basic 6.0 ช่วยในการเขียนโปรแกรมแปลง CLfile Data



รูปที่ ข – 1 แสดงโปรแกรม CLfile Data Proe 2000i²

โดยมีรายละเอียด Code ของโปรแกรมมีดังนี้

Option Explicit

```

Private Sub cmdFileIn_Click()
    CommonDialog1.ShowOpen
    txtFileIn = CommonDialog1.FileName
End Sub

Private Sub cmdFileOut_Click()
    CommonDialog1.ShowSave
    txtFileOut = CommonDialog1.FileName
End Sub

Private Sub Command2_Click()
```

```

If txtFileIn = "" Then
    MsgBox "æ×í; File Input"
    Exit Sub
End If

Dim sRecord      As String

' Dim sID          As String
Dim sParse        As String
Dim sBuffer       As String
Dim iReadFile     As Integer
Dim iWriteFile    As Integer
Dim bFirstLine    As Boolean
Dim sCurrentPath As String
Screen.MousePointer = vbHourglass
DoEvents

' bFirstLine = True

iReadFile = FreeFile
iWriteFile = FreeFile
sCurrentPath = App.Path + "\"
Open txtFileIn For Input As #iReadFile

'Open File (text files)
Dim fs, a
Dim i As Integer
Dim Str2Wrt As String
Dim str1 As String
Dim str2 As String

```

```

Set fs = CreateObject("Scripting.FileSystemObject")
Set a = fs.CreateTextFile(sCurrentPath + Trim(txtFileOut), True)

Dim xPos As Integer

Do Until EOF(iReadFile)
    ***** read file into a buffer string *****
    Select Case LOF(iReadFile) - Seek(iReadFile)
        Case 0
            If sParse = "" Then
                Exit Do
            End If
            If InStr(sParse, vbLf) = 0 Then
                Exit Do
            End If
        'This size is for a 1.44 Disc
        Case Is >= 142000
            sBuffer = Input(LOF(iReadFile) - Seek(iReadFile) + 1, iReadFile)
            sParse = sParse & sBuffer
        Case Is < 142000
            On Error Resume Next
            sBuffer = Input(LOF(iReadFile) - Seek(iReadFile) + 1, iReadFile)
            sParse = sParse & sBuffer
    End Select

    ***** read string *****
    Select Case lblAxis
        Case 6 ' 6 áí
            While InStr(sParse, vbCr) Or Len(sParse) > 4

```

```

If InStr(sParse, "GOTO") = 1 Then

    str1 = Left(sParse, InStr(sParse, vbLf) - 4)
    sParse = Mid(sParse, InStr(sParse, vbLf) + 1)

    str2 = Left(sParse, InStr(sParse, vbLf) - 1)
    sParse = Mid(sParse, InStr(sParse, vbLf) + 1)

    a.WriteLine (CutForAddSign(str1, str2))

Else
    sParse = Mid(sParse, InStr(sParse, vbLf) + 1)
    If Len(sParse) = 31 Then Exit Do
    End If
    DoEvents
    Wend

Case 3
    While InStr(sParse, vbCr) Or Len(sParse) > 4
        If InStr(sParse, "GOTO") = 1 Then

            str1 = Left(sParse, InStr(sParse, vbLf) - 1)
            sParse = Mid(sParse, InStr(sParse, vbLf) + 1)

            'str2 = Left(sParse, InStr(sParse, vbLf) - 1)
            'sParse = Mid(sParse, InStr(sParse, vbLf) + 1)

            a.WriteLine (CutForAddSign(str1, str2))

        Else
            sParse = Mid(sParse, InStr(sParse, vbLf) + 1)
        End If
    End While
End If

```

```
If Len(sParse) = 31 Then Exit Do
End If
DoEvents
Wend
End Select
DoEvents
Loop

MsgBox "Finished Text Transfer"

Close #iReadFile
Close #iWriteFile
Dim xx
xx = Shell("C:\WINDOWS\NOTEPAD.EXE " + App.Path + "\" + txtFileOut, vbNormalFocus)

Screen.MousePointer = vbArrow

End Sub

Function CutForAddSign(xStr1 As String, xStr2 As String) As String
On Error GoTo x

Dim str1 As String
Dim str2 As String

Dim StrCut As String

Dim strRemain As String

Dim c1 As String
```

```

Dim c2 As String
Dim c3 As String
Dim c4 As String
Dim c5 As String
Dim c6 As String

Dim p1 As Integer
Dim p2 As Integer

Dim preStr As String
strRemain = xStr1 + xStr2
preStr = lblFormatType

p1 = InStr(strRemain, "/")
p2 = InStr(strRemain, ",")
c1 = "X " + Mid(strRemain, p1 + 2, p2 - 8)
strRemain = Mid(strRemain, p2 + 1)

p2 = InStr(strRemain, ",")
c2 = "Y " + Mid(strRemain, 1, p2 - 1)
strRemain = Mid(strRemain, p2 + 1)

If lblAxis = 3 Then
    c3 = "Z " + strRemain
    CutForAddSign = preStr + " " + "{" + c1 + "," + c2 + "," + c3 + "}"
Else
    p2 = InStr(strRemain, ",")
    c3 = "Z " + Mid(strRemain, 1, p2 - 1)
    strRemain = Mid(strRemain, p2 + 1)

```

```

p1 = InStr(strRemain, "/")
p2 = InStr(strRemain, ",")  

If p1 = 0 Then  

    c4 = "A " + Mid(strRemain, 1, p2 - 1) ' ÄÖ $ íÅÙè'éÇÂ
Else  

    c4 = "A " + Mid(strRemain, p1 + 2, p2 - 11) ' ÄÖ $ íÅÙè'éÇÂ
End If  

strRemain = Mid(strRemain, p2 + 1)

p2 = InStr(strRemain, ",")  

c5 = "B " + Mid(strRemain, 1, p2 - 1)
strRemain = Mid(strRemain, p2 + 1)

p2 = InStr(strRemain, ",")  

If p2 = 0 Then  

    c6 = "C " + strRemain
Else  

    c6 = "C " + Mid(strRemain, 1, p2 - 1)
End If  

CutForAddSign = preStr + " " + "{" + c1 + "," + c2 + "," + c3 + "," + c4 + "," + c5 + "," + c6
+ "}""
End If

Exit Function

x:  

Screen.MousePointer = vbArrow
MsgBox Error + vbCr + vbLf + " ÈÃ×íÍÓ"”ÐÁÖ»Ñ-ÈÒaÃ×èí§ File á¹ÃÙ»áºº 6 á¡¹ ÈÃ×í 3 á¡¹
", vbCritical

End

```

```
'Resume 'Next  
End Function  
  
Private Sub Form_Load()  
    Option1_Click(0)  
    optAxis_Click(1)  
End Sub  
  
Private Sub optAxis_Click(Index As Integer)  
    Select Case Index  
        Case 0  
            lblAxis = 6  
        Case 1  
            lblAxis = 3  
    End Select  
  
End Sub  
  
Private Sub Option1_Click(Index As Integer)  
    Select Case Index  
        Case 0  
            lblFormatType = "PTP"  
        Case 1  
            lblFormatType = "CIRC"  
        Case 2  
            lblFormatType = "LIN"  
    End Select  
End Sub
```